



WARNING: DO NOT CRIMP OR OVER-BEND FLUID LINES AT FITTINGS WHILE SECURING LINES TO BOTTOM OF TABLE

USE NYLON CLIPS SUPPLIED TO SECURE LIFT SYSTEM LINES TO BOTTOM OF WORK SURFACE (4 PLACES)

MOUNT STRUT 8"-10" BELOW WORK SURFACE

WARNING: DO NOT CRIMP OR OVER-BEND FLUID LINES AT FITTINGS WHILE SECURING LINES TO BOTTOM OF TABLE

COIL EXCESS LIFT LINES AS NECESSARY AND SECURE WITH WIRE TIES THROUGH NYLON CLIP AS SHOWN

WARNING: MAKE COIL 2" RADIUS OR LARGER. DO NOT OVER-BEND OR CRIMP TUBES. DAMAGE TO LIFT SYSTEM MAY RESULT.

WARNING: DO NOT USE INNER HOLES OR DAMAGE TO LIFT SYSTEM LINES MAY OCCUR! (RIGHT SIDE SHOWN)

NOTE: PLATE ORIENTATION (CUPPED SIDE UP)

NOTE: CYLINDER WASHER ORIENTATION

ITEM QTY	NAME
1	10 #10-32 x 3/4" TRILOBULAR THREAD CUTTING PFTHS
2	3 #10 x 2-1/2" SHEET METAL SCREW
3	8 #14 x 3/4" SHEET METAL SCREW
4	1 TABLE TOP
5	1 LEVITTECH LIFT ASSEMBLY
6	2 LEG ASSEMBLY
7	2 TOP MOUNTING PLATE
8	1 5/32 ALLEN WRENCH
9	2 CYLINDER WASHER
10	4 #10-32 x 1-1/4" SOCKET HD CAP SCREW
11	2 NUT PLATE
12	1 STRUT
13	8 #10-32 x 1/2" PHILLIPS PAN HEAD SCREW
14	2 FOOT
15	4 GLIDE
16	4 TUBE CAP
17	2 PLATE
18	6 3/16" DIA LOOP STRAP (#8876T15)
19	6 #6 WOOD SCREW
20	8 #10-32 x 1" TRILOBULAR HEX DRIVE WASHER HEAD THREAD ROLLING SCREW